CAPITAL WORKS PLAN


TOWERING HEIGHTS

at 1 SMITH STREET SYDNEY Plan No. SP 00000

L&P Job No. 99902/12345

Prepared by L&P Quantity Surveyor Blake Rooney BAppSc(QS), AIQS(Affil.)

Printed: 16 December 2016



LEARY & PARTNERS PTY LTD

ABN 010 134 148 Quantity Surveyors Asset Management Consultants Taxation Depreciation Consultants Registered Tax Agent 53798007

> Telephone 1800 808 991 www.leary.com.au enquiries@leary.com.au

©Leary & Partners Pty Ltd 2016

SUMMARY OF CONTRIBUTIONS

15 YEAR PLAN 15 YEAR FORECAST: Starting October 2016

for

TOWERING HEIGHTS SP 00000

Prepared by Leary & Partners Pty Ltd - Job No. 99902 Dated : 24 November 2016 Fund Balance @ October 2016: \$24,113.00

| For the 12 month period ending | Total Contributions+ | Expected Requirements | Fund Balance* | Interest less Tax |
|--------------------------------|-------------------------|--------------------------|--------------------|-------------------|
| 30-09-2017 | \$137,397 | \$13,229 | \$149,789 | \$1,508 |
| 30-09-2018 | \$142,893 | \$13,758 | \$282,675 | \$3,751 |
| 30-09-2019 | \$148,609 | \$14,309 | \$423,097 | \$6,122 |
| 30-09-2020 | \$154,553 | \$18,987 | \$567,253 | \$8,590 |
| 30-09-2021 | \$160,735 | \$31,348 | \$707 <i>,</i> 700 | \$11,059 |
| 30-09-2022 | \$167,165 | \$22,436 | \$866,079 | \$13,651 |
| 30-09-2023 | \$173,851 | \$30,877 | \$1,025,461 | \$16,407 |
| 30-09-2024 | \$180,805 | \$60,352 | \$1,164,913 | \$19,000 |
| 30-09-2025 | \$188,037 | \$323,739 | \$1,048,410 | \$19,199 |
| 30-09-2026 | \$195,559 | \$502,164 | \$757,470 | \$15,664 |
| 30-09-2027 | \$203,381 | \$85,101 | \$890,041 | \$14,291 |
| 30-09-2028 | \$211,517 | \$168,107 | \$949,406 | \$15,956 |
| 30-09-2029 | \$219,977 | \$310,077 | \$875,133 | \$15,826 |
| 30-09-2030 | \$228,776 | \$266,389 | \$852,506 | \$14,986 |
| 30-09-2031 | \$237,927 | \$1,053,004 | \$45,216 | \$7,787 |

*This balance includes interest earned on the fund balance and tax payable on these earnings. We were advised that this scheme is registered for GST.

+GST needs to be added to the Total Contributions when levying the residents

Expected Inflation4.00%Contingency10.00%Interest2.50%Taxation30.00%

PREAMBLE CLAUSES

1.00 PURPOSE OF CAPITAL WORKS PLAN

The purpose of this report is to enable the owners corporation to make adequate monetary provision for future common property replacements and major repair items, in accordance with the requirements of the relevant legislation.

2.00 LEGISLATION

This survey has been prepared with reference to the Strata Schemes Management Act 2015. It does not take into account the impact of future changes to this legislation or to other relevant legislation (eg. The Work Place Health and Safety Legislation).

3.00 THE GOODS AND SERVICES TAX

This report was produced for an entity required to be <u>registered</u> for the GST. The cost estimates allow for indirect increases to the base cost of materials and labour due to the introduction of the GST, but excludes the GST imposed on maintenance and repair works undertaken by the village operator.

4.00 BASIS OF COST FORECASTS

Expenses have been forecast in line with the standard requirements for a building of this nature and assume a typical level of usage and maintenance.

The cost allowances in this report are our best estimate of the likely future costs, based on the information available to us at this date. These cost estimates may be impacted by factors that cannot be reasonably foreseen at this time. Common examples of such factors include unusual market conditions at the time of the works, associated remedial works being required, special access or scaffolding being required or the owners corporation choosing to vary the repaired or replaced infrastructure. Further, when competitive quotes are sought, there is normally a variation between the quoted prices.

For these reasons we recommend that the owners corporation obtain competitive quotes for major work items (including the external painting) at least twelve months in advance of the forecast work date.

5.00 STRUCTURAL DEFECTS AND REFURBISHMENTS

This is not a structural report and does not cover expenditure that occurs either directly or indirectly as a result of structural defects. It does not cover expenditure as a result of accidental damage. An asbestos detection survey has not been undertaken and no allowance has been made for removal of asbestos.

Refurbishments undertaken for reasons other than physical obsolescence have not been included apart from where the owners corporation has provided us with budgeted costs. Physical obsolescence is the basis by which the remaining and overall lives have been investigated. No allowance has been made for economic, functional, technological, social, and legal obsolescence.

6.00 ADMINISTRATIVE BUDGET ITEMS NOT INCLUDED

The cost of maintenance contract items normally included in the Administrative budget have not been included in this forecast.

7.00 CONTRIBUTION SCHEDULE

The "Contributions Optimisation Chart" graphs how the contribution scheme relates to the expected requirements and the capital works fund balances over the full forecast period. When calculating the contributions we :

- ensure that there are always sufficient funds to meet the forecast requirements,

- try to achieve a steadily increasing contribution scheme,
- ensure that the owners corporation is not unduly contributing funds,
- investigate the expected requirements over the full forecast period, not just the first ten years.

The contributions shown in italics in the "Variable Contributions for 10 Year Plan" are draft figures only which should be reviewed on an annual basis to take into consideration actual expenses

incurred, the actual capital works fund balance and additions or changes to the building.

8.00 CAPITAL WORKS FUND BALANCE

The levy for the current financial year was set prior to the preparation of this report. The capital works fund balance used in this forecast is therefore an estimate only, based on the last known balance, expected contributions and recorded expenses.

The capital works fund balance used in the forecast is the last known balance shown in the owners corporation records.

9.00 CONTINGENCY

The contingency sum has been included to allow for unforeseen expenses that may occur during the life of this forecast.

10.00 FORECAST PERIOD

This report is calculated to run from the date stated on the cover page, in twelve-month periods.

11.00 EXPLANATION OF ABBREVIATIONS

The capital works fund forecast uses the following abbreviations :

FR: First Replacement

RC: Replacement Cycle

12.00 PLAN AND FORECAST PERIOD

- **12.01** The term 'plan', shown on the first page of this report, refers to the period for which levies have been calculated.
- **12.02** The term 'forecast', shown on the first page of this report, refers to the period of time over which maintenance and repair costs are assessed.
- **12.03** This report includes only work items that are expected to occur during the report forecast period. Items of work expected to occur at a date further into the future will be added at a later date as part of the ongoing forecast update process.

13.00 INSPECTION INFORMATION

Please note the following information relating to this report.

- 13.01 Our report is based on the following :
 - data collected on site at the date of inspection
 - information provided by strata management
- **13.02** The survey has been prepared with reference to the plan SP 00000.Supplementary architectural drawings were not provided during the survey preparation.
- **13.03** The recommendations in this report are based on a visual inspection of the development undertaken from the ground level and accessible building areas. No physically destructive or intrusive testing was carried out.
- **13.04** Where an item has been included to replace aluminium windows or window hardware, this item does not include for any work to unit balcony doors. We believe these doors are within the lot boundaries and are therefore the responsibility of the lot owner. An allowance has been made to paint only the previously painted surfaces including external surfaces extending into lot boundaries.
- **13.05** The allowance for painting does not include for special hoarding or other special safety provision that may be a requirement of the local council.
- **13.06** If your building has a lift it has been assumed that the lift plant and equipment is covered by a comprehensive service agreement. Please inform our office if this is not the case.
- **13.07** The item included in the forecast for the replacement of underground pipework is a contingency allowance only. The location of the pipework and its condition were unable to be determined.
- **13.08** Assuming materials and workmanship were of a reasonable standard during construction, some infrastructure items should only require partial ongoing replacement or repair during the plan

period. For these items, an estimated percentage of the total quantity/cost has been used to allow for the partial replacement or repair of these items. (This allowance may change in future forecasts to reflect a greater maintenance requirement during those future periods.)

- replacing co2 detectors
- replacing small ventilation fans and motors
- replacing stormwater pump
- replacing light fittings
- replacing large ventilation fans and motors
- replacing exposed internal ductwork
- replacing emergency light fittings
- replacing dks card readers
- replacing door hardware
- replacing fire extinguisher
- replacing fire hose reel and nozzle
- replacing aluminium window hardware
- replacing balcony / terrace membrane
- replacing hard floor finishes
- replacing timberwork to floor and seats
- replacing bollard lights
- replacing external wall lights
- replacing membrane to podium slab
- replacing underground pipework
- replacing ventilation fans and motors
- replacing built up roofing membrane
- replacing fire detectors
- replacing mirrors

We recommend the status of these items be reviewed at regular intervals.

| EXP | ECTED REC | QUIREMENTS | | | | FR | RC | 12 mths ending | 12 mths ending |
|------------|-----------|---|------|--------|---------|------|-----|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|----------------|
| ltem | Area | Description | Unit | Qty. | Rate | Yrs | Yrs | 30-09-17 | 30-09-18 | 30-09-19 | 30-09-20 | 30-09-21 | 30-09-22 | 30-09-23 | 30-09-24 | 30-09-25 | 30-09-26 |
| | | | | | | | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| #1 | Basement | Repaint carpark line markings | m | 1,694 | | - | 5 | | | | | 5,142 | | | | | 6,256 |
| #2 | Basement | Replace waterfall filteration equipment | Item | | 2,805 | | 7 | | | | | | | 3,599 | | | <u> </u> |
| #3 | Basement | Replace CO2 detectors (approx. 20%) | No. | | 5 385 | + + | 2 | | | | | | | 2,470 | | 2,671 | |
| #4 | Basement | Replace small ventilation fans and motors (approx. 20%) | No. | 3 | 3 1,375 | | 4 | | | | | | | | 5,504 | | |
| #5 | Basement | Replace stormwater pump (approx. 50%) | No. | | 2 1,980 | | 5 | | | | | | | | 5,284 | | |
| #6 | Basement | Replace variable speed drive | No. | 3 | 3 1,375 | + + | 9 | | | | | | | | | 5,724 | |
| #7 | Basement | Replace sewerage pump | No. | - | 1 3,850 | | 9 | | | | | | | | | 5,342 | |
| #8 | Basement | Replace automatic basement door opening gear | No. | - | 1 1,823 | 8 9 | 9 | | | | | | | | | 2,530 | |
| #9 | Basement | Paint common basement areas | m2 | 443 | 3 15 | 5 11 | 12 | | | | | | | | | | |
| #10 | Basement | Replace light fittings (approx. 10%) | No. | 26 | 6 191 | . 11 | 2 | | | | | | | | | | |
| #11 | Basement | Replace bin room floor membrane | m2 | 89 | 9 33 | 8 11 | 12 | | | | | | | | | | |
| #12 | Basement | Replace electric hot water unit | No. | - | 1 605 | 5 11 | 11 | | | | | | | | | | |
| #13 | Basement | Maintain fire booster pumps | No. | 2 | 2 4,950 |) 12 | 10 | | | | | | | | | | |
| #14 | Basement | Replace fire jacking pump - large | No. | 1 | 1 5,225 | 5 12 | 12 | | | | | | | | | | |
| #15 | Basement | Replace large ventilation fans and motors (approx. 30%) | No. | - | 1 3,575 | 5 12 | 5 | | | | | | | | | | |
| #16 | Basement | Replace fire jacking pump - small | No. | - | 1 1,375 | 5 12 | 12 | | | | | | | | | | |
| #17 | Basement | Replace water supply booster pumps | No. | 2 | 2 9,075 | 5 13 | 13 | | | | | | | | | | |
| #18 | Basement | Replace exposed internal ductwork (approx. 10%) | m2 | 66 | 6 187 | / 14 | 12 | | | | | | | | | | |
| #19 | Basement | Replace basement door | No. | | 1 8,531 | . 14 | 14 | | | | | | | | | | |
| #20 | Basement | Maintain floor tiles | m2 | 22 | 1 166 | 5 14 | 10 | | | | | | | | | | |
| #21 | Building | Replace emergency light fittings (approx. 10%) | No. | 20 | 198 | 3 4 | 1 | | | | 4,516 | 4,697 | 4,885 | 5,080 | 5,284 | 5,495 | 5,715 |
| #22 | Building | Replace DKS card readers (approx. 25%) | No. | | 4 424 | 6 | 3 | | | | | | 2,090 | | | 2,351 | |
| #23 | Building | Replace CCTV system | Item | | 6,930 | 8 | 8 | | | | | | | | 9,246 | | |
| #24 | Building | Replace door hardware (approx. 5%) | No. | 12 | 2 396 | 5 9 | 2 | | | | | | | | | 6,594 | |
| #25 | Building | Replace fire extinguisher (approx. 30%) | No. | 10 | 209 | 9 | 4 | | | | | | | | | 2,900 | |
| #26 | Building | Paint building facade | m2 | 12,690 | 28 | 3 10 | 10 | | | | | | | | | | 507,445 |
| #27 | Building | Replace air conditioner to manager office | Item | , | 2,529 | | 11 | | | | | | | | | | |
| #28 | Building | Maintain glazed aluminium balustrade | m | 49 | | 3 12 | 10 | | | | | | | | | | |
| #29 | Building | Replace MATV system components | Item | | 13,024 | + + | 12 | | | | | | | | | | |
| #30 | Building | Replace fire hose reel and nozzle (approx. 25%) | No. | 10 | - | 5 12 | 5 | | | | | | | | | | |
| #31 | Building | Replace intercom system | Item | | 62,480 | | 13 | | | | | | | | | | |
| #32 | Building | Replace aluminium window hardware (approx. 20%) | No. | 178 | - | 5 13 | 5 | | | | | | | | | | |
| #33 | Building | Replace balcony / terrace membrane (approx. 5%) | m2 | 152 | | 5 14 | 5 | | | | | | | | | | <u> </u> |
| #34 | Building | Replace fire indicator panels | Item | | 20,625 | | 14 | | | | | | | | | | |
| #34 | Building | Replace hard floor finishes (approx. 2.5%) | m2 | 74 | - | 5 14 | 5 | | | | | | | | | | |
| #36 | Building | Refurbish bathrooms | Item | | 11,000 | | 15 | | | | | | | | | | |
| #30 #37 | External | Replace timberwork to floor and seats (approx. 50%) | m2 | 30 | - | / 8 | 4 | | | | | | | | 11,104 | | <u> </u> |
| #37 #38 | External | Maintain external tiling | m2 | 32 | | 2 12 | 5 | | | | | | | | 11,104 | | |
| #38 #39 | External | Replace bollard lights (approx. 30%) | No. | | | 12 | 6 | | | | | | | | | | |
| #39 #40 | External | Replace external wall lights (approx. 30%) | No. | | | 3 12 | 6 | | | | | | | | | | + |
| #40 #41 | External | Replace membrane to podium slab (approx. 5%) | m2 | 8 | | 3 13 | 5 | | | | | | | | | | |
| #41 #42 | | Replace underground pipework (approx. 20%) | ltem | | 25,146 | | 15 | | | | | | | | | | |
| #42 #43 | External | Replace membrane to ponds | m2 | 140 | |) 14 | 15 | | | | | | | | | | <u> </u> |
| | External | | | | | | | | | | | | | | | | + |
| #44 | External | Maintain metal fence | m | 36 | D 196 | 5 14 | 10 | | | | | | | | | | L |

| | | | | | | | | 12 mths |
|------|-----------------|--|------|------|--------|-------|-----|----------|----------|----------|----------|----------|----------|----------|----------|----------|----------|
| EXF | PECTED REQU | UIREMENTS | | | | FR | RC | ending |
| ltem | Area | Description | Unit | Qty. | Rate | Yrs | Yrs | 30-09-17 | 30-09-18 | 30-09-19 | 30-09-20 | 30-09-21 | 30-09-22 | 30-09-23 | 30-09-24 | 30-09-25 | 30-09-26 |
| | | | | | | | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| #45 | External | Maintain external balustrades | m | | 13 33 | 86 14 | 12 | | | | | | | | | | |
| #46 | External | Maintain concrete paving | m2 | 2 | 90 | 1 14 | 10 | | | | | | | | | | |
| #47 | External | Replace letterboxes | Item | | 13,1 | 2 15 | 15 | | | | | | | | | | |
| #48 | Lifts | Replace lift components | Item | | 608,3 | 0 15 | 15 | | | | | | | | | | |
| #49 | Lifts | Replace lift carriage interior | No. | | 4 13,2 | 0 15 | 15 | | | | | | | | | | |
| #50 | Roof | Replace hot water circulating pump | No. | | 8 8 |)3 5 | 6 | | | | | 7,620 | | | | | |
| #51 | Roof | Replace ventilation fans and motors (approx. 7.5%) | No. | | 2 1,7 | 6 7 | 1 | | | | | | | 4,403 | 4,579 | 4,762 | 4,953 |
| #52 | Roof | Replace gas hot water instant heater | No. | | 13 2,3 | 59 | 10 | | | | | | | | | 41,760 | |
| #53 | Roof | Replace gas hot water storage tank | No. | | 4 3,0 | 4 9 | 10 | | | | | | | | | 16,729 | |
| #54 | Roof | Replace hot water booster pump | No. | | 4 1,3 | 75 9 | 10 | | | | | | | | | 7,632 | |
| #55 | Roof | Replace built up roofing membrane (approx. 20%) | m2 | 5 | 82 | 9 13 | 4 | | | | | | | | | | |
| #56 | Stairwells | Replace light fittings (approx. 10%) | No. | | 2 1 | 91 10 | 2 | | | | | | | | | | 552 |
| #57 | Typical lobbies | Replace fire detectors (approx. 10%) | No. | | 25 1 | 87 8 | 1 | | | | | | | | 6,238 | 6,487 | 6,747 |
| #58 | Typical lobbies | Replace carpet | m2 | 1,3 | 28 | 64 9 | 10 | | | | | | | | | 118,377 | |
| #59 | Typical lobbies | Paint walls and ceilings | m2 | 4,7 | 57 | 59 | 10 | | | | | | | | | 99,837 | |
| #60 | Typical lobbies | Replace light fittings (approx. 10%) | No. | | 34 14 | 19 9 | 2 | | | | | | | | | 7,006 | |
| #61 | Typical lobbies | Maintain floor tiles | m2 | | 28 10 | 6 12 | 10 | | | | | | | | | | |
| #62 | Typical lobbies | Replace mirrors (approx. 25%) | m2 | | 12 24 | 19 14 | 8 | | | | | | | | | | |
| #63 | Typical lobbies | Replace signage to unit doors | No. | 1 | 48 | 28 15 | 15 | | | | | | | | | | |
| #64 | | Tax credit claim for GST component | | | | | | -1,323 | -1,376 | -1,431 | -1,899 | -3,135 | -2,244 | -3,088 | -6,035 | -32,374 | -50,216 |
| | | Contingency | | | | | | 14,552 | 15,134 | 15,740 | 16,369 | 17,024 | 17,705 | 18,413 | 19,150 | 19,916 | 20,712 |
| | Total | | | | | | | 13,229 | 13,758 | 14,309 | 18,987 | 31,348 | 22,436 | 30,877 | 60,352 | 323,739 | 502,164 |

| EXP | ECTED REG | QUIREMENTS | 12 mths ending |
|------|-----------|---|-------------------|-------------------|-------------------|-------------------|-------------------|
| ltem | Area | Description | 30-09-27 11 | 30-09-28 12 | 30-09-29 13 | 30-09-30 14 | 30-09-31 15 |
| #1 | Basement | Repaint carpark line markings | | | | | 7,612 |
| #2 | Basement | Replace waterfall filteration equipment | | | | 4,735 | |
| #3 | Basement | Replace CO2 detectors (approx. 20%) | 2,889 | | 3,125 | | 3,380 |
| #4 | Basement | Replace small ventilation fans and motors (approx. 20%) | | 6,439 | | | |
| #5 | Basement | Replace stormwater pump (approx. 50%) | | | 6,428 | | |
| #6 | Basement | Replace variable speed drive | | | | | |
| #7 | Basement | Replace sewerage pump | | | | | |
| #8 | Basement | Replace automatic basement door opening gear | | | | | |
| #9 | Basement | Paint common basement areas | 10,140 | | | | |
| #10 | Basement | Replace light fittings (approx. 10%) | 7,469 | | 8,078 | | 8,737 |
| #11 | Basement | Replace bin room floor membrane | 4,408 | | | | |
| #12 | Basement | Replace electric hot water unit | 908 | | | | |
| #13 | Basement | Maintain fire booster pumps | | 15,453 | | | |
| #14 | Basement | Replace fire jacking pump - large | | 8,156 | | | |
| #15 | Basement | Replace large ventilation fans and motors (approx. 30%) | | 5,580 | | | |
| #16 | Basement | Replace fire jacking pump - small | | 2,146 | | | |
| #17 | Basement | Replace water supply booster pumps | | | 29,463 | | |
| #18 | Basement | Replace exposed internal ductwork (approx. 10%) | | | | 20,836 | |
| #19 | Basement | Replace basement door | | | | 14,401 | |
| #20 | Basement | Maintain floor tiles | | | | 5,889 | |
| #21 | Building | Replace emergency light fittings (approx. 10%) | 5,943 | 6,181 | 6,428 | 6,685 | 6,953 |
| #22 | Building | Replace DKS card readers (approx. 25%) | | 2,644 | | | 2,974 |
| #23 | Building | Replace CCTV system | | | | | |
| #24 | Building | Replace door hardware (approx. 5%) | 7,132 | | 7,714 | | 8,343 |
| #25 | Building | Replace fire extinguisher (approx. 30%) | | | 3,393 | | |
| #26 | Building | Paint building facade | | | | | |
| #27 | Building | Replace air conditioner to manager office | 3,795 | | | | |
| #28 | Building | Maintain glazed aluminium balustrade | | 44,169 | | | |
| #29 | Building | Replace MATV system components | | 20,329 | | | |
| #30 | Building | Replace fire hose reel and nozzle (approx. 25%) | | 7,726 | | | |
| #31 | Building | Replace intercom system | | | 101,424 | | |
| #32 | Building | Replace aluminium window hardware (approx. 20%) | | | 24,601 | | |
| #33 | Building | Replace balcony / terrace membrane (approx. 5%) | | | | 55,368 | |
| #34 | Building | Replace fire indicator panels | | | | 34,820 | |
| #35 | Building | Replace hard floor finishes (approx. 2.5%) | | | | 20,613 | |
| #36 | Building | Refurbish bathrooms | | | | | 19,313 |
| #37 | External | Replace timberwork to floor and seats (approx. 50%) | | 12,990 | | | |
| #38 | External | Maintain external tiling | | 7,356 | | | |
| #39 | External | Replace bollard lights (approx. 30%) | | 1,978 | | | |
| #40 | External | Replace external wall lights (approx. 30%) | | 858 | | | |
| #41 | External | Replace membrane to podium slab (approx. 5%) | | | 12,089 | | |
| #42 | External | Replace underground pipework (approx. 20%) | | | - | 42,452 | |
| #43 | External | Replace membrane to ponds | | | | 18,979 | |
| #44 | External | Maintain metal fence | | | | 11,900 | |

| | | | 12 mths |
|------|-----------------|--|----------|----------|----------|----------|-----------|
| EXP | ECTED REQ | UIREMENTS | ending | ending | ending | ending | ending |
| ltem | Area | Description | 30-09-27 | 30-09-28 | 30-09-29 | 30-09-30 | 30-09-31 |
| | | | 11 | 12 | 13 | 14 | 15 |
| #45 | External | Maintain external balustrades | | | | 7,363 | |
| #46 | External | Maintain concrete paving | | | | 5,385 | |
| #47 | External | Replace letterboxes | | | | | 23,022 |
| #48 | Lifts | Replace lift components | | | | | 929,736 |
| #49 | Lifts | Replace lift carriage interior | | | | | 92,704 |
| #50 | Roof | Replace hot water circulating pump | 9,641 | | | | |
| #51 | Roof | Replace ventilation fans and motors (approx. 7.5%) | 5,151 | 5,357 | 5,571 | 5,794 | 6,026 |
| #52 | Roof | Replace gas hot water instant heater | | | | | |
| #53 | Roof | Replace gas hot water storage tank | | | | | |
| #54 | Roof | Replace hot water booster pump | | | | | |
| #55 | Roof | Replace built up roofing membrane (approx. 20%) | | | 93,687 | | |
| #56 | Stairwells | Replace light fittings (approx. 10%) | | 597 | | 646 | |
| #57 | Typical lobbies | Replace fire detectors (approx. 10%) | 7,016 | 7,297 | 7,589 | 7,892 | 8,208 |
| #58 | Typical lobbies | Replace carpet | | | | | |
| #59 | Typical lobbies | Paint walls and ceilings | | | | | |
| #60 | Typical lobbies | Replace light fittings (approx. 10%) | 7,578 | | 8,196 | | 8,865 |
| #61 | Typical lobbies | Maintain floor tiles | | 7,259 | | | |
| #62 | Typical lobbies | Replace mirrors (approx. 25%) | | | | 5,036 | |
| #63 | Typical lobbies | Replace signage to unit doors | | | | | 7,232 |
| #64 | | Tax credit claim for GST component | -8,510 | -16,811 | -31,008 | -26,639 | -105,300 |
| | | Contingency | 21,541 | 22,402 | 23,299 | 24,231 | 25,200 |
| | Total | | 85,101 | 168,107 | 310,077 | 266,389 | 1,053,004 |

SUMMARISED SINKING FUND BUDGET FORECAST

10 YEAR PLAN - 15 YEAR FORECAST : Starting October 2016

for

TOWERING HEIGHTS SP 00000

Prepared by Leary & Partners Pty Ltd - Job No. 99902

1.0 General Information

The contributions shown in this report are based on a 15 year forecast period, i.e. the forecast calculations take into account the replacement and maintenance requirements of the building over the next 15 years. This report displays the forecast contributions and expenses for the first ten years of this period.

2.0 Current Sinking Fund Balance

The starting sinking fund balance used in these calculations is \$24,113.00 as at 1 October 2016.

3.0 Summary of Required Sinking Fund Contributions

These contributions have been calculated to ensure that sufficient funds are available to meet all foreseeable expenses. The calculations take into account the current balance of the body corporate's sinking fund, as well as the effect of inflation, interest earnings and taxation.

| For Period | to |
|---------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| | Sep-17 | Sep-18 | Sep-19 | Sep-20 | Sep-21 | Sep-22 | Sep-23 | Sep-24 | Sep-25 | Sep-26 |
| Total Sinking Fund Contribution | \$137,397 | \$142,893 | \$148,609 | \$154,553 | \$160,735 | \$167,165 | \$173,851 | \$180,805 | \$188,037 | \$195,559 |
| Contribution per Entitlement | \$13.74 | \$14.29 | \$14.86 | \$15.46 | \$16.07 | \$16.72 | \$17.39 | \$18.08 | \$18.80 | \$19.56 |

GST needs to be added to the Total Contributions when levying the Lot owners.

4.0 Summary of Expected Expenditure

The table below is a summary of the forecast sinking fund expenditure for the next ten years. A contingency allowance has been included to provide for general unforeseen expenses which may occur during the forecast period. Detailed information about the expense items listed in this summary are contained in an extended forecast report. If you wish to view the extended report please contact your Body Corporate or Body Corporate Manager.

| | | | | Expect | ed Sinking F | und Require | ements | | | |
|------------------------------------|----------|----------|----------|----------|--------------|-------------|----------|----------|-----------------|-----------|
| Categories | to | to | to | to | to | to | to | to | to | to |
| | Sep-17 | Sep-18 | Sep-19 | Sep-20 | Sep-21 | Sep-22 | Sep-23 | Sep-24 | Sep-25 | Sep-26 |
| Doors & Other Openings | | | | | | 2,090 | | 9,246 | 11,474 | |
| Floor Coverings | | | | | | | | | 118,377 | |
| Surface Finishes | | | | | 5,142 | | | | 99 <i>,</i> 837 | 513,701 |
| Air Handling Systems | | | | | | | 4,403 | 10,083 | 10,486 | 4,953 |
| Electrical Systems | | | | 4,516 | 4,697 | 4,885 | 5,080 | 5,284 | 12,501 | 6,267 |
| Fire Equipment | | | | | | | 2,470 | 6,238 | 12,058 | 6,747 |
| Pumps & Motors | | | | | | | 3,599 | 5,284 | 5,342 | |
| Hot Water Installations | | | | | 7,620 | | | | 66,121 | |
| External Timberwork | | | | | | | | 11,104 | | |
| Contingency | 14,552 | 15,134 | 15,740 | 16,369 | 17,024 | 17,705 | 18,413 | 19,150 | 19,916 | 20,712 |
| Tax credit claim for GST component | -1,323 | -1,376 | -1,431 | -1,899 | -3,135 | -2,244 | -3,088 | -6,035 | -32,374 | -50,216 |
| Total Expected Expenditure | \$13,229 | \$13,758 | \$14,309 | \$18,987 | \$31,348 | \$22,436 | \$30,877 | \$60,352 | \$323,739 | \$502,164 |

Variable Contributions for 10 Year Plan

| Lot No. | Entitl. | 2016-17 | 2017-18 | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 | 2024-25 | 2025-26 |
|---------|---------|----------|----------|----------|----------|----------|----------|----------|----------|---------------|---------------|
| L1 | 73 | 1,003.00 | 1,043.12 | 1,084.84 | 1,128.24 | 1,173.37 | 1,220.30 | 1,269.11 | 1,319.88 | 1,372.67 | 1,427.58 |
| L2 | 86 | 1,181.62 | 1,228.88 | 1,278.04 | 1,329.16 | 1,382.32 | 1,437.62 | 1,495.12 | 1,554.93 | 1,617.12 | 1,681.81 |
| L3 | 44 | 604.55 | 628.73 | 653.88 | 680.03 | 707.23 | 735.52 | 764.95 | 795.54 | 827.36 | 860.46 |
| L4 | 63 | 865.60 | 900.23 | 936.24 | 973.68 | 1,012.63 | 1,053.14 | 1,095.26 | 1,139.07 | 1,184.64 | 1,232.02 |
| L5 | 68 | 934.30 | 971.67 | 1,010.54 | 1,050.96 | 1,093.00 | 1,136.72 | 1,182.19 | 1,229.48 | 1,278.65 | 1,329.80 |
| L6 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L7 | 57 | 783.16 | 814.49 | 847.07 | 880.95 | 916.19 | 952.84 | 990.95 | 1,030.59 | 1,071.81 | 1,114.69 |
| L8 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L9 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L10 | 69 | 948.04 | 985.96 | 1,025.40 | 1,066.42 | 1,109.07 | 1,153.44 | 1,199.57 | 1,247.56 | 1,297.46 | 1,349.36 |
| L11 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L12 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L13 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L14 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L15 | 70 | 961.78 | 1,000.25 | 1,040.26 | 1,081.87 | 1,125.15 | 1,170.15 | 1,216.96 | 1,265.64 | 1,316.26 | 1,368.91 |
| L16 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L17 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L18 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L19 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L20 | 70 | 961.78 | 1,000.25 | 1,040.26 | 1,081.87 | 1,125.15 | 1,170.15 | 1,216.96 | 1,265.64 | 1,316.26 | 1,368.91 |
| L21 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| L22 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L23 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L24 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L25 | 71 | 975.52 | 1,014.54 | 1,055.12 | 1,097.33 | 1,141.22 | 1,186.87 | 1,234.34 | 1,283.72 | 1,335.07 | 1,388.47 |
| L26 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L27 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L28 | 72 | 989.26 | 1,028.83 | 1,069.98 | 1,112.78 | 1,157.29 | 1,203.59 | 1,251.73 | 1,301.80 | 1,353.87 | 1,408.02 |
| L29 | 73 | 1,003.00 | 1,043.12 | 1,084.84 | 1,128.24 | 1,173.37 | 1,220.30 | 1,269.11 | 1,319.88 | 1,372.67 | 1,427.58 |
| L30 | 95 | 1,305.27 | 1,357.48 | 1,411.78 | 1,468.25 | 1,526.98 | 1,588.06 | 1,651.59 | 1,717.65 | 1,786.36 | 1,857.81 |
| L31 | 107 | 1,470.15 | 1,528.96 | 1,590.11 | 1,653.72 | 1,719.87 | 1,788.66 | 1,860.21 | 1,934.62 | 2,012.00 | 2,092.48 |
| L32 | 86 | 1,181.62 | 1,228.88 | 1,278.04 | 1,329.16 | 1,382.32 | 1,437.62 | 1,495.12 | 1,554.93 | 1,617.12 | 1,681.81 |
| L33 | 73 | 1,003.00 | 1,043.12 | 1,084.84 | 1,128.24 | 1,173.37 | 1,220.30 | 1,269.11 | 1,319.88 | , 1,372.67 | , 1,427.58 |
| | | - | - | - | - | - | - | - | - | | |

| Lot No. | Entitl. | 2016-17 | 2017-18 | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 | 2024-25 | 2025-26 |
|---------|---------|----------|----------|-------------|----------|----------|----------|----------|----------|----------|----------|
| L34 | 73 | 1,003.00 | 1,043.12 | 1,084.84 | 1,128.24 | 1,173.37 | 1,220.30 | 1,269.11 | 1,319.88 | 1,372.67 | 1,427.58 |
| L35 | 58 | 796.90 | 828.78 | 861.93 | 896.41 | 932.26 | 969.55 | 1,008.34 | 1,048.67 | 1,090.62 | 1,134.24 |
| L35 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L30 | 68 | 934.30 | 971.67 | 1,010.54 | 1,050.96 | 1,093.00 | 1,136.72 | 1,182.19 | 1,229.48 | 1,278.65 | 1,329.80 |
| L38 | 62 | 851.86 | 885.94 | 921.37 | 958.23 | 996.56 | 1,036.42 | 1,077.88 | 1,120.99 | 1,165.83 | 1,212.47 |
| L39 | 44 | 604.55 | 628.73 | 653.88 | 680.03 | 707.23 | 735.52 | 764.95 | 795.54 | 827.36 | 860.46 |
| L40 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L41 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L42 | 69 | 948.04 | 985.96 | 1,025.40 | 1,066.42 | 1,109.07 | 1,153.44 | 1,199.57 | 1,247.56 | 1,297.46 | 1,349.36 |
| L43 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L44 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L45 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L46 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L47 | 70 | 961.78 | 1,000.25 | 1,040.26 | 1,081.87 | 1,125.15 | 1,170.15 | 1,216.96 | 1,265.64 | 1,316.26 | 1,368.91 |
| L48 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L49 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L50 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L51 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L52 | 70 | 961.78 | 1,000.25 | 1,040.26 | 1,081.87 | 1,125.15 | 1,170.15 | 1,216.96 | 1,265.64 | 1,316.26 | 1,368.91 |
| L53 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L54 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L55 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L56 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L57 | 71 | 975.52 | 1,014.54 | 1,055.12 | 1,097.33 | 1,141.22 | 1,186.87 | 1,234.34 | 1,283.72 | 1,335.07 | 1,388.47 |
| L58 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L59 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L60 | 106 | 1,456.41 | 1,514.67 | 1,575.25 | 1,638.26 | 1,703.79 | 1,771.94 | 1,842.82 | 1,916.54 | 1,993.20 | 2,072.92 |
| L61 | 96 | 1,319.01 | 1,371.77 | 1,426.64 | 1,483.71 | 1,543.06 | 1,604.78 | 1,668.97 | 1,735.73 | 1,805.16 | 1,877.37 |
| L62 | 73 | 1,003.00 | 1,043.12 | 1,084.84 | 1,128.24 | 1,173.37 | 1,220.30 | 1,269.11 | 1,319.88 | 1,372.67 | 1,427.58 |
| L63 | 72 | 989.26 | 1,028.83 | 1,069.98 | 1,112.78 | 1,157.29 | 1,203.59 | 1,251.73 | 1,301.80 | 1,353.87 | 1,408.02 |
| L64 | 54 | 741.94 | 771.62 | 802.49 | 834.59 | 867.97 | 902.69 | 938.80 | 976.35 | 1,015.40 | 1,056.02 |
| L65 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L66 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L67 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L68 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L69 | 46 | 632.03 | 657.31 | 683.60 | 710.94 | 739.38 | 768.96 | 799.72 | 831.70 | 864.97 | 899.57 |
| L70 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| 270 | | 010.04 | 0.0.07 | 0, 0, , , , | 511.00 | 5 10.54 | 500.27 | 1,020.72 | 1,000.75 | 1,100.12 | 1,100.0 |


| Lot No. | Entitl. | 2016-17 | 2017-18 | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 | 2024-25 | 2025-26 |
|---------|---------|---------|---------|----------|----------|----------|----------|----------|----------|----------|----------|
| L71 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L72 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L73 | 45 | 618.29 | 643.02 | 668.74 | 695.49 | 723.31 | 752.24 | 782.33 | 813.62 | 846.17 | 880.02 |
| L74 | 45 | 618.29 | 643.02 | 668.74 | 695.49 | 723.31 | 752.24 | 782.33 | 813.62 | 846.17 | 880.02 |
| L75 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L76 | 47 | 645.77 | 671.60 | 698.46 | 726.40 | 755.46 | 785.67 | 817.10 | 849.78 | 883.78 | 919.13 |
| L77 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L78 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L79 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L80 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L81 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L82 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L83 | 47 | 645.77 | 671.60 | 698.46 | 726.40 | 755.46 | 785.67 | 817.10 | 849.78 | 883.78 | 919.13 |
| L84 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L85 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L86 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L87 | 62 | 851.86 | 885.94 | 921.37 | 958.23 | 996.56 | 1,036.42 | 1,077.88 | 1,120.99 | 1,165.83 | 1,212.47 |
| L88 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L89 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L90 | 47 | 645.77 | 671.60 | 698.46 | 726.40 | 755.46 | 785.67 | 817.10 | 849.78 | 883.78 | 919.13 |
| L91 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L92 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L93 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| L94 | 63 | 865.60 | 900.23 | 936.24 | 973.68 | 1,012.63 | 1,053.14 | 1,095.26 | 1,139.07 | 1,184.64 | 1,232.02 |
| L95 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L96 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L97 | 48 | 659.51 | 685.89 | 713.32 | 741.85 | 771.53 | 802.39 | 834.49 | 867.87 | 902.58 | 938.68 |
| L98 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| L99 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| L100 | 68 | 934.30 | 971.67 | 1,010.54 | 1,050.96 | 1,093.00 | 1,136.72 | 1,182.19 | 1,229.48 | 1,278.65 | 1,329.80 |
| L101 | 63 | 865.60 | 900.23 | 936.24 | 973.68 | 1,012.63 | 1,053.14 | 1,095.26 | 1,139.07 | 1,184.64 | 1,232.02 |
| L102 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L103 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L104 | 48 | 659.51 | 685.89 | 713.32 | 741.85 | 771.53 | 802.39 | 834.49 | 867.87 | 902.58 | 938.68 |
| L105 | 68 | 934.30 | 971.67 | 1,010.54 | 1,050.96 | 1,093.00 | 1,136.72 | 1,182.19 | 1,229.48 | 1,278.65 | 1,329.80 |
| L106 | 68 | 934.30 | 971.67 | 1,010.54 | 1,050.96 | 1,093.00 | 1,136.72 | 1,182.19 | 1,229.48 | 1,278.65 | 1,329.80 |
| L107 | 69 | 948.04 | 985.96 | 1,025.40 | 1,066.42 | 1,109.07 | 1,153.44 | 1,199.57 | 1,247.56 | 1,297.46 | 1,349.36 |

| Lot No. | Entitl. | 2016-17 | 2017-18 | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 | 2024-25 | 2025-26 |
|---------|---------|----------|----------|----------|---------------|---------------|----------|---------------|----------|----------|---------------|
| L108 | 63 | 865.60 | 900.23 | 936.24 | 973.68 | 1,012.63 | 1,053.14 | 1,095.26 | 1,139.07 | 1,184.64 | 1,232.02 |
| L109 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| L110 | 119 | 1,635.03 | 1,700.43 | 1,768.44 | 1,839.18 | 1,912.75 | 1,989.26 | 2,068.83 | 2,151.58 | 2,237.65 | 2,327.15 |
| L111 | 118 | 1,621.29 | 1,686.14 | 1,753.58 | 1,823.73 | 1,896.68 | 1,972.54 | 2,051.44 | 2,133.50 | 2,218.84 | 2,307.60 |
| L112 | 59 | 810.64 | 843.07 | 876.79 | 911.86 | 948.34 | 986.27 | 1,025.72 | 1,066.75 | 1,109.42 | 1,153.80 |
| L113 | 70 | 961.78 | 1,000.25 | 1,040.26 | 1,081.87 | 1,125.15 | 1,170.15 | 1,216.96 | 1,265.64 | 1,316.26 | 1,368.91 |
| L114 | 70 | 961.78 | 1,000.25 | 1,040.26 | 1,081.87 | 1,125.15 | 1,170.15 | 1,216.96 | 1,265.64 | 1,316.26 | 1,368.91 |
| L115 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L116 | 77 | 1,057.96 | 1,100.28 | 1,144.29 | 1,190.06 | 1,237.66 | 1,287.17 | 1,338.65 | 1,392.20 | 1,447.89 | 1,505.80 |
| L117 | 48 | 659.51 | 685.89 | 713.32 | 741.85 | 771.53 | 802.39 | 834.49 | 867.87 | 902.58 | 938.68 |
| L118 | 71 | 975.52 | 1,014.54 | 1,055.12 | 1,097.33 | 1,141.22 | 1,186.87 | 1,234.34 | 1,283.72 | 1,335.07 | 1,388.47 |
| L119 | 64 | 879.34 | 914.52 | 951.10 | 989.14 | 1,028.71 | 1,069.85 | 1,112.65 | 1,157.15 | 1,203.44 | 1,251.58 |
| L120 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L121 | 78 | 1,071.70 | 1,114.57 | 1,159.15 | 1,205.51 | 1,253.73 | 1,303.88 | 1,356.04 | 1,410.28 | 1,466.69 | 1,525.36 |
| L122 | 75 | 1,030.48 | 1,071.70 | 1,114.57 | 1,159.15 | 1,205.51 | 1,253.73 | 1,303.88 | 1,356.04 | 1,410.28 | 1,466.69 |
| L123 | 71 | 975.52 | 1,014.54 | 1,055.12 | 1,097.33 | 1,141.22 | 1,186.87 | 1,234.34 | 1,283.72 | 1,335.07 | 1,388.47 |
| L124 | 65 | 893.08 | 928.80 | 965.96 | 1,004.60 | 1,044.78 | 1,086.57 | 1,130.03 | 1,175.23 | 1,222.24 | 1,271.13 |
| L125 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L126 | 81 | 1,112.92 | 1,157.43 | 1,203.73 | 1,251.88 | 1,301.96 | 1,354.03 | 1,408.19 | 1,464.52 | 1,523.10 | 1,584.03 |
| L127 | 75 | 1,030.48 | 1,071.70 | 1,114.57 | 1,159.15 | 1,205.51 | 1,253.73 | 1,303.88 | 1,356.04 | 1,410.28 | 1,466.69 |
| L128 | 71 | 975.52 | 1,014.54 | 1,055.12 | 1,097.33 | 1,141.22 | 1,186.87 | 1,234.34 | 1,283.72 | 1,335.07 | 1,388.47 |
| L129 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L130 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L131 | 80 | 1,099.18 | 1,143.14 | 1,188.87 | 1,236.42 | 1,285.88 | 1,337.32 | 1,390.81 | 1,446.44 | 1,504.30 | 1,564.47 |
| L132 | 76 | 1,044.22 | 1,085.99 | 1,129.43 | 1,174.60 | 1,221.59 | 1,270.45 | 1,321.27 | 1,374.12 | 1,429.08 | 1,486.25 |
| L133 | 72 | 989.26 | 1,028.83 | 1,069.98 | 1,112.78 | 1,157.29 | 1,203.59 | 1,251.73 | 1,301.80 | 1,353.87 | 1,408.02 |
| L134 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L135 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L136 | 81 | 1,112.92 | 1,157.43 | 1,203.73 | 1,251.88 | 1,301.96 | 1,354.03 | 1,408.19 | 1,464.52 | 1,523.10 | 1,584.03 |
| L137 | 77 | 1,057.96 | 1,100.28 | 1,144.29 | 1,190.06 | 1,237.66 | 1,287.17 | 1,338.65 | 1,392.20 | 1,447.89 | 1,505.80 |
| L138 | 73 | 1,003.00 | 1,043.12 | 1,084.84 | , 1,128.24 | , 1,173.37 | 1,220.30 | , 1,269.11 | 1,319.88 | 1,372.67 | , 1,427.58 |
| L139 | 66 | 906.82 | 943.09 | 980.82 | 1,020.05 | 1,060.85 | 1,103.29 | 1,147.42 | 1,193.31 | 1,241.05 | 1,290.69 |
| L140 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| L141 | 82 | 1,126.66 | 1,171.72 | 1,218.59 | 1,267.34 | 1,318.03 | 1,370.75 | 1,425.58 | 1,482.60 | 1,541.91 | 1,603.58 |
| L142 | 78 | 1,071.70 | 1,114.57 | 1,159.15 | 1,205.51 | 1,253.73 | 1,303.88 | 1,356.04 | 1,410.28 | 1,466.69 | 1,525.36 |
| L143 | 74 | 1,016.74 | 1,057.41 | 1,099.70 | 1,143.69 | 1,189.44 | 1,237.02 | 1,286.50 | 1,337.96 | 1,391.48 | 1,447.14 |
| L144 | 67 | 920.56 | 957.38 | 995.68 | 1,035.51 | 1,076.93 | 1,120.00 | 1,164.80 | 1,211.40 | 1,259.85 | 1,310.25 |
| 6744 | 07 | 520.50 | 557.50 | 555.00 | 1,000.01 | 1,070.33 | 1,120.00 | 1,104.00 | 1,211.40 | 1,203.00 | 1,510.25 |

| Lot No. | Entitl. | 2016-17 | 2017-18 | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 | 2024-25 | 2025-26 |
|---------|---------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| L145 | 100 | 1,373.97 | 1,428.93 | 1,486.09 | 1,545.53 | 1,607.35 | 1,671.65 | 1,738.51 | 1,808.05 | 1,880.37 | 1,955.59 |
| L146 | 119 | 1,635.03 | 1,700.43 | 1,768.44 | 1,839.18 | 1,912.75 | 1,989.26 | 2,068.83 | 2,151.58 | 2,237.65 | 2,327.15 |
| L147 | 112 | 1,538.85 | 1,600.40 | 1,664.42 | 1,730.99 | 1,800.23 | 1,872.24 | 1,947.13 | 2,025.02 | 2,106.02 | 2,190.26 |
| L148 | 121 | 1,662.51 | 1,729.01 | 1,798.17 | 1,870.09 | 1,944.90 | 2,022.69 | 2,103.60 | 2,187.74 | 2,275.25 | 2,366.26 |
| Totals | 10000 | \$137,397.13 | \$142,893.01 | \$148,608.73 | \$154,553.08 | \$160,735.21 | \$167,164.62 | \$173,851.20 | \$180,805.25 | \$188,037.46 | \$195,558.96 |
| | | | | | | | | | | | |

*The contributions shown in italics should be reviewed on an annual basis.

*GST needs to be added to the Total Contributions when levying the Lot owners.



Site Photographs